

UT165 MP Tool Release Note-V1.65.6.0.txt

Ver 1.65.1.0

1. First formal release
2. Support Samsung 50nm flash only

Ver 1.65.2.0

1. Fix power cycling 0 issue
2. Update F/W

Ver 1.65.5.0

1. Modify format size of K9LAG08U0A Dual channel.
2. Fix some 2k flash 0x88 issue.
3. Solved Power cycling issue.
4. Solved K9HCG08U1M 16CE MP error.
5. Add no read status function for UT165.
6. Improve Readdy Boost performance for Intel flash 29F16G08AAMC1.
7. Disable cache program function for MLC flash.
8. Close "F10 quicktest" function.

Ver 1.65.6.0

1. Delete "F1"select device UT163 function